

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|------------------------------|------------------------|--------------|-------------------------|--------------|
| Type of Inspection: | Annual | Date: | 5/2/2019 | Time: | 10:47 AM |
| Name of School Corporation: | OAK HILL UNITED SCHOOL CORP. | | | Corp ID: | 525625 |
| Address of School Corporation: | PO Box 550 | | | | |
| City: | Converse | Zip: | 46919 | County Number: | 52 |
| VIN: | 4UZABRDXCCBA1230 | License Number: | 1112 | Bus Number: | 10 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2011 | Make of Chassis: | Freightliner |
| Bus Type: | C | Year: | 2012 | Mileage: | 86669 |
| Inspection Status: | R | Inspected By: | Randy McPike | PE: | 7018 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 2-1-1 | Required back-up lights do not function. |
| 90-1-3 | The trash container is not secured to prevent movement and does not allow for easy removal and replacement |
| 28-1-4 | The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction. |
| 50-1-2 | The seat belt cutter is not secured using a positive fastening method. |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.