

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/2/2019	Time:	11:48 AM		
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625		
Address of School Corporation:	PO Box 550						
City:	Converse	Zip:	46919	County Number:	52		
VIN:	4DRBUAFN08B493714	License Number:	30640	Bus Number:	12		
Make of Body:	IC Corporation	Year:	2007	Make of Chassis:	IC Corporation	Year:	2008
Bus Type:	C	Mileage:	115916	PE:	7018		
Inspection Status:	R	Inspected By:	Randy McPike				

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
68-1-1	Washers do not function properly in any manner
46-1-2	Any seat back or bottom is loose
26-1-4	Not securely mounted

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.