REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection		Date:	5/9/2019	Time:	1:36 PM
Name of School Corporation:		OAK HILL UNITED SCHOOL CORP.		Corp ID:	525625	
Address of School	Corporation:	PO Box 550				
City:	Converse	Zip:	46919		County Number	52
VIN:	4DRBUSKN29	B095305	License Number:	30876	Bus Number:	7
Make of Body:	IC Corporation	Year: 2008	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	С		Mileage:	129858		
Inspection Status:	А	Inspected By	: Randy McPike		PE:	7018

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.