

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	5/15/2019	Time:	8:28 AM
Name of School Corporation:	M.S.D. DECATUR TOWNSHIP	Corp ID:	495300		
Address of School Corporation:	5251 Kentucky Ave				
City:	Indianapolis	Zip:	46221	County Number:	49
VIN:	4UZABRFC5LCLM2935	License Number:	00000	Bus Number:	25
Make of Body:	Thomas Built Buses, Inc.	Year:	2018	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C	Mileage:	4230	Year:	2020
Inspection Status:	O	Inspected By:	John Pang	PE:	6196

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-1	Any headlight is inoperative
64-1-4	Any front turn signal does not function properly
64-1-2	A lens is cracked, missing or wrong color
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
67-1-5	See Notes: Any defect inspector deems a violation not listed
36-1-1	The latch does not secure the hood tightly

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.

