

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/16/2019	Time:	11:31 AM
Name of School Corporation:	LEWIS-CASS SCHOOL CORPORATION			Corp ID:	90815
Address of School Corporation:	6422 E SR 218				
City:	Walton	Zip:	46994	County Number:	9
VIN:	4DRBWTAR9KB330244	License Number:	22130	Bus Number:	711
Make of Body:	IC Corporation	Year:	2018	Make of Chassis:	IC Corporation
Year:	2018	Year:	2019	Year:	2019
Bus Type:	D	Mileage:	14949	PE:	7018
Inspection Status:	O	Inspected By:	Randy McPike		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.