

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 5/17/2019	<b>Time:</b> 8:33 AM
<b>Name of School Corporation:</b> LEWIS-CASS SCHOOL CORPORATION	<b>Corp ID:</b> 90815	
<b>Address of School Corporation:</b> 6422 E SR 218		
<b>City:</b> Walton	<b>Zip:</b> 46994	<b>County Number:</b> 9
<b>VIN:</b> 4DRBWAAR9EB016585	<b>License Number:</b> 7055	<b>Bus Number:</b> 313
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2013	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2014	<b>Mileage:</b> 94403	<b>PE:</b> 7018
<b>Bus Type:</b> D	<b>Inspected By:</b> Randy McPike	
<b>Inspection Status:</b> R		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
59-1-7	Any optional rear stop arm device or school bus crossing arm criteria is not met
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
52-1-1	There are any loose, broken, or missing mountings

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**