## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Re-InspectionDate:5/17/2019Time:4:23 PMName of School Corporation:DELAWARE COMM. SCHOOL CORP.Corp ID:181875

Address of School Corporation: 7821 SR 3 N

City:MuncieZip:47303County Number:18VIN:4DRAPSKH29A674247License Number:715775Bus Number:2Make of Body:IC Corporation Year:2009

Bus Type: Mileage: 66303

Inspection Status: A Inspected By: Jamie Hotchkiss PE: 6458

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

**Bus Type Description**