## REPORT OF SCHOOL BUS INSPECTION

Type of 11:28 Time: Annual Date: 5/20/2019 Inspection: AM Name of School Corporation: CRAWFORDSVILLE COMM. SCHOOLS 545855 Corp ID: **Address of School Corporation:** 1000 Fairview Ave County City: Crawfordsville Zip: 47933 54 Number: License VIN: 1T7YT4C2681297914 20456 Bus Number: 28 Number: Thomas Built Buses, Year: 2007 Thomas Built Buses, Year: Make of Make of Body: 2008 Inc. Chassis: Inc. **Bus Type:** D Mileage: 95474 Inspection Inspected PE: R Nate King 7421 Status: By:

## **Violations - Rejected**

Inspection Code	<u>Description</u>
22-1-1	A dripping oil or fluid leak
52-1-4	Any shock absorber is broken or missing
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.