## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual		Date:	5/28/2019	Time:	9:29 AM
Name of School Corporation:		ILIO SERVICES	(MUNCIE)		Corp ID:	251807
Address of School	Corporation:	11260 Cornell	Park Dr Suite 700			
City:	Cincinnati	Zip:	45242		<b>County Number:</b>	18
VIN:	4DRBUC8P6GB724	480	License Number:	B516N	Bus Number:	M14
Make of Body:	IC Corporation Year	: 2014	Make of Chassis:	IC Corporation	Year:	2016
Bus Type:	С		Mileage:	32786		
Inspection Status:	0	Inspected By:	Jamie Hotchkiss		PE:	6458

**Violations - Rejected** 

Inspection Code	<b>Description</b>
52-1-2	Any shock absorber is leaking fluid

## Violations - Out of Service

Inspection Code	<b>Description</b>
64-2-1	Any rear turn signal does not function properly

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.