REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection		Date:	5/29/2019	Time:	9:17 AM
Name of Schoo Address of Sch	I Corporation: MA ool Corporation:		SCHOOL CORPO wtown Pike	DRATION	Corp ID:	525615
City:	Bunker Hill	Zip:	46914		County Number:	52
VIN:	1T88Y9D23J1128755		License Number:	16616	Bus Number:	16
Make of Body:	Thomas Built Buses, Yea Inc.	r: 2017	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2018
Bus Type:	D		Mileage:	26659		
Inspection Status:	0	Inspected By:	Randy McPike		PE:	7018

Violations - Rejected

<u>Inspection</u> <u>Code</u>	<u>Description</u>			
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.			
23-1-6	Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the bus body			
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)			
31-1-3	See Notes: Any defect inspector deems a violation not listed			

Violations - Out of Service

Inspection Code	<u>Description</u>
20-2-2	Door glass is missing

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.