

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                               |                        |              |                         |          |
|---------------------------------------|-------------------------------|------------------------|--------------|-------------------------|----------|
| <b>Type of Inspection:</b>            | Annual                        | <b>Date:</b>           | 5/30/2019    | <b>Time:</b>            | 10:23 AM |
| <b>Name of School Corporation:</b>    | ELWOOD COMMUNITY SCHOOL CORP. |                        |              | <b>Corp ID:</b>         | 485280   |
| <b>Address of School Corporation:</b> | 1306 N Anderson St            |                        |              |                         |          |
| <b>City:</b>                          | Elwood                        | <b>Zip:</b>            | 46036        | <b>County Number:</b>   | 48       |
| <b>VIN:</b>                           | 1GDHG31F3X1065346             | <b>License Number:</b> | 25960        | <b>Bus Number:</b>      | A1       |
| <b>Make of Body:</b>                  | Corbeil                       | <b>Year:</b>           | 1999         | <b>Make of Chassis:</b> | GMC      |
| <b>Bus Type:</b>                      |                               | <b>Mileage:</b>        | 59130        | <b>Year:</b>            | 1999     |
| <b>Inspection Status:</b>             | A                             | <b>Inspected By:</b>   | Jeremy Mason | <b>PE:</b>              | 8139     |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| <u>Bus Type</u> | <u>Description</u> |
|-----------------|--------------------|
|-----------------|--------------------|