## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual		Date:	5/30/2019	Time:	10:10 AM
Name of School	•		OLIDATED SCH. C	ORP.	Corp ID:	232435
Address of School Corporation:		205 College St				
City:	Attica	Zip:	47918		County Number:	23
VIN:	1BAKGCPH0CF28	37515	License Number:	2417	Bus Number:	2
Make of Body:	Blue Bird Corporation	Year: 2011	Make of Chassis:	Blue Bird Corporation	Year:	2012
Bus Type:	С		Mileage:	70834		
Inspection Status:	R	Inspecte By:	ed Nate King		PE:	7421

## **Violations - Rejected**

Inspection<br/>CodeDescription23-1-3Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any<br/>direction (with the engine idling and the system unrestricted).

**Violations - Out of Service** 

Inspection Code Description

## Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.