## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual Date: 6/4/2019 **Time**: 9:25 AM

Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP

Corp ID: 131300

**Address of School Corporation:** 5808 E Administration Rd

City: Marengo Zip: 47140 County Number: 13 VIN: **Bus Number:** 1gb6g5bg0c1110997 License Number: 3443 43 Chevrolet Year: 2012 Make of Chassis: Chevrolet Year: 2012 Make of Body:

**Bus Type:** Α1 Mileage: 100453

**Inspection Status:** R Inspected By: Mike Adams PE: 7407

## **Violations - Rejected**

**Description Inspection Code** 

62-1-2 One (1) taillight or one (1) brake light does not function

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.