

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	6/5/2019	<b>Time:</b>	9:11 AM		
<b>Name of School Corporation:</b>	BETHANY CHRISTIAN SCHOOLS	<b>Corp ID:</b>	20B015				
<b>Address of School Corporation:</b>	2904 S Main St						
<b>City:</b>	Goshen	<b>Zip:</b>	46526	<b>County Number:</b>	20		
<b>VIN:</b>	1GB3G2BG1B1110703	<b>License Number:</b>	B914F	<b>Bus Number:</b>	MB6		
<b>Make of Body:</b>	Star Trans	<b>Year:</b>	2011	<b>Make of Chassis:</b>	Chevrolet	<b>Year:</b>	2011
<b>Bus Type:</b>	B	<b>Mileage:</b>	74741				
<b>Inspection Status:</b>	A	<b>Inspected By:</b>	Wes Rowlander	<b>PE:</b>	7427		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.