

## REPORT OF SCHOOL BUS INSPECTION

|                                                              |                                    |                                   |
|--------------------------------------------------------------|------------------------------------|-----------------------------------|
| <b>Type of Inspection:</b> Annual                            | <b>Date:</b> 6/5/2019              | <b>Time:</b> 9:11 AM              |
| <b>Name of School Corporation:</b> BETHANY CHRISTIAN SCHOOLS | <b>Corp ID:</b> 20B015             |                                   |
| <b>Address of School Corporation:</b> 2904 S Main St         |                                    |                                   |
| <b>City:</b> Goshen                                          | <b>Zip:</b> 46526                  | <b>County Number:</b> 20          |
| <b>VIN:</b> 1GB3G2BG1B1110703                                | <b>License Number:</b> B914F       | <b>Bus Number:</b> MB6            |
| <b>Make of Body:</b> Star Trans                              | <b>Year:</b> 2011                  | <b>Make of Chassis:</b> Chevrolet |
| <b>Year:</b> 2011                                            |                                    |                                   |
| <b>Bus Type:</b> B                                           | <b>Mileage:</b> 74741              |                                   |
| <b>Inspection Status:</b> R                                  | <b>Inspected By:</b> Wes Rowlander | <b>PE:</b> 7427                   |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>            |
|------------------------|-------------------------------|
| 17-1-1                 | Any dome light is inoperative |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**