

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 5/17/2019	Time: 12:20 PM	
Name of School Corporation: CLAY COMMUNITY SCHOOLS		Corp ID: 111125	
Address of School Corporation: PO Box 169			
City: Knightsville	Zip: 47857	County Number: 11	
VIN: 1BAKFCSA7KF353151	License Number: 353151	Bus Number: 36	
Make of Body: Blue Bird Corporation	Year: 2018	Make of Chassis: Blue Bird Corporation	Year: 2019
Bus Type: C	Mileage: 13987		
Inspection Status: O	Inspected By: Byron Goodman	PE: 7008	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.