REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection			Date:	6/17/2019	Time:	8:44 AM
Name of School Corporation: Address of School Corporation:		SOUT	SOUTHWESTERN CON SCH SHELBY 3406 W 600 S		′ CO	Corp ID:	737360
City:	Shelbyville		Zip:	46176		County Number:	73
VIN:	1GBJG31U061151320			License Number:	69396	Bus Number:	17
Make of Body:	Collins Bus Corporation	Year:	2005	Make of Chassis:	Chevrolet	Year:	2006
Bus Type:	С			Mileage:	128697		
Inspection Status:	0		Inspected By:	Chris Clark		PE:	6665

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

44-1-1 Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

Inspection Code	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed
8-2-5	There is brake fluid leaking at any point
41-2-1	Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students)
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half (½) inch in diameter.
20-2-1	Is no audible signal when the emergency door is open and ignition switch is on

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.