## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual Date: 6/20/2019 **Time**: 1:11 PM Name of School Corporation: CULVER COMMUNITY SCHOOLS CORP.

Corp ID: 505455

**Address of School Corporation:** PO Box 231

City: Culver Zip: 46511 **County Number:** 50 VIN: 1HA6GUBG4JN005614 **Bus Number:** License Number: 62447 24 Chevrolet Year: 2018 2019 Make of Body: Make of Chassis: Starcraft Year:

**Bus Type:** Α1 Mileage: 9019

PE: **Inspection Status:** R **Inspected By:** Gamaliel Reeves 8352

## **Violations - Rejected**

## **Description Inspection Code**

50-1-2 The seat belt cutter is not secured using a positive fastening method.

Violations - Out of Service

**Inspection Code Description** 

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.