

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 6/19/2019	Time: 10:38 AM
Name of School Corporation: SOUTHWEST PARKE COMM SCH CORP	Corp ID: 616260	
Address of School Corporation: RR 1		
City: Montezuma	Zip: 47862	County Number: 61
VIN: 4DRBUAAN6CB553639	License Number: B989K	Bus Number: 10
Make of Body: IC Corporation	Year: 2011	Make of Chassis: IC Corporation
Year: 2012	Mileage: 73700	PE: 7008
Bus Type: C	Inspected By: Byron Goodman	
Inspection Status: O		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.