REPORT OF SCHOOL BUS INSPECTION

Type of Annual Date: 6/19/2019 Time: 11:18 AM

Name of School Corporation: SOUTHWEST PARKE COMM SCH CORP Corp ID: 616260

Address of School Corporation: RR 1

City: Montezuma Zip: 47862 County Number: 61

VIN: 4DRBUAAP6DB163921 License Number: 14643 Bus Number: SWP14

Make of Body: IC Corporation Year: 2012 Make of Chassis: IC Corporation Year: 2013

Bus Type: C Mileage: 53937

Inspection Status: O Inspected By: Byron Goodman PE: 7008

Violations - Rejected

Inspection Code Description

24-1-2 The bus body has loose, damaged or improperly aligned body parts. These would

include rivets, bolts, and body panels and/or rub rails

65-1-8 See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.