

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/19/2019	Time:	11:18 AM
Name of School Corporation:	SOUTHWEST PARKE COMM SCH CORP	Corp ID:	616260		
Address of School Corporation:	RR 1				
City:	Montezuma	Zip:	47862	County Number:	61
VIN:	4DRBUAAP6DB163921	License Number:	14643	Bus Number:	SWP14
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	53937	Year:	2013
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
65-1-8	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.