REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/19/2019	**Time:**	11:37 AM
Name of School Corporation:	SOUTHWEST PARKE COMM SCH CORP			**Corp ID:**	616260
Address of School Corporation:	RR 1				
City:	Montezuma	**Zip:**	47862	**County Number:**	61
VIN:	4DRBUAAP7BB334530	**License Number:**	74623	**Bus Number:**	SWP1
Make of Body:	IC Corporation **Year:** 2010	**Make of Chassis:**	IC Corporation	**Year:**	2011
Bus Type:	C	**Mileage:**	104891		
Inspection Status:	O	**Inspected By:**	Byron Goodman	**PE:**	7008

Violations - Rejected

Inspection Code	Description
65-1-1	Any lens is cracked, broken or discolored

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.