

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|--------------------------------|------------------------|---------------|-----------------|------------------|----------------|-------|------|
| Type of Inspection: | Annual | Date: | 7/10/2019 | Time: | 11:25 AM | | |
| Name of School Corporation: | SCHOOL CITY OF HAMMOND | | | Corp ID: | 454710 | | |
| Address of School Corporation: | 5727 Sohl Ave | | | | | | |
| City: | Hammond | Zip: | 46320 | County Number: | 45 | | |
| VIN: | 4DRAPS88BB343538 | | License Number: | 74937 | Bus Number: | 157 | |
| Make of Body: | IC Corporation | Year: | 2010 | Make of Chassis: | IC Corporation | Year: | 2011 |
| Bus Type: | B | | | Mileage: | 82980 | | |
| Inspection Status: | A | Inspected By: | Tim Grayson | PE: | 7558 | | |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.