## REPORT OF SCHOOL BUS INSPECTION

Type of 8:20 Annual Time: Date: 7/12/2019 Inspection: AM Name of School Corporation: CROWN POINT COMM. SCHOOL CORP. Corp ID: 454660 **Address of School Corporation:** 1151 E Summit County City: Crown Point Zip: 46307 45 Number: License VIN: 4UZABRFC3LCLU8488 22935 **Bus Number: 46** Number: Thomas Built Buses, Year: 2019 Thomas Built Buses, Year: Make of Make of Body: 2020 Chassis: Inc. **Bus Type:** С Mileage: 730 Inspection Inspected PE: 7558 Α Tim Grayson Status: By:

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.