

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	7/12/2019	Time:	11:31 AM
Name of School Corporation:	CARROLL CONS. SCHOOL CORP.	Corp ID:	80750		
Address of School Corporation:	2 S 3rd St.				
City:	Flora	Zip:	46929	County Number:	8
VIN:	4DRBUAAP78B498840	License Number:	31624	Bus Number:	23
Make of Body:	IC Corporation	Year:	2008	Make of Chassis:	IC Corporation
Year:	2008	Year:	2008	Year:	2008
Bus Type:	C	Mileage:	144264	PE:	7421
Inspection Status:	O	Inspected By:	Nate King		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
18-2-3	Center/carrier bearing: any broken or loose center/carrier bearing bracket, bolts or mounting hardware, any center bearing bracket crack equaling fifty (50) percent or more of the original width, more than one half (1/2) inch vertical movement of the shaft in the center bearing carrier (rubber)

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.