REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	7/12/2019	Time:	11:38 AM
Name of School Co	orporation: CAR	ROLL CONS. SO	CHOOL CORP.		Corp ID:	80750
Address of School	Corporation:	2 S 3rd St.				
City:	Flora	Zip:	46929		County Number:	8
VIN:	4DRBUSKP0FB529	945	License Number:	7413	Bus Number:	21
Make of Body:	IC Corporation Year	: 2015	Make of Chassis:	IC Corporation	Year:	2015
Bus Type:	С		Mileage:	67992		
Inspection Status:	R	Inspected By:	Nate King		PE:	7421

Violations - Rejected

Inspection CodeDescription23-1-5Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.