REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	7/12/2019	Time:	11:52 AM
Name of School Corporation:	CAR	ROLL CONS.	SCHOOL CORP.		Corp ID:	80750
Address of Schoo	I Corporation:	2 S 3rd St.				
City:	Flora	Zip:	46929		County Number:	8
VIN:	1GB3GSBL9G	1324634	License Number:	48588	Bus Number:	2sb
Make of Body:	Chevrolet Year	: 2016	Make of Chassis:	Collins Bus Corporation	Year:	2016
Bus Type:	С		Mileage:	42901		
Inspection Status	: A	Inspected By:	Nate King		PE:	7421

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.