REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	7/12/2019	Time:	12:16 PM
Name of School Co	prporation:	CARROLL C	CONS. SC	CHOOL CORP.		Corp ID:	80750
Address of School	Corporation:	2 S 3r	d St.				
City:	Flora	Zip:		46929		County Number:	8
VIN:	4DRBUC8P8G	B121465		License Number:	10247	Bus Number:	14
Make of Body:	IC Corporation	Year: 2016		Make of Chassis:	IC Corporation	Year:	2016
Bus Type:	С			Mileage:	43105		
Inspection Status:	R	Inspe	cted By:	Nate King		PE:	7421

Violations - Rejected

Inspection Code

Description There are any leaks from the differential, pinion seal, hubs or wheel seals 16-1-1

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.