

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 7/12/2019      **Time:** 12:29 PM  
**Name of School Corporation:** CARROLL CONS. SCHOOL CORP.      **Corp ID:** 80750  
**Address of School Corporation:** 2 S 3rd St.  
**City:** Flora      **Zip:** 46929      **County Number:** 8  
**VIN:** 1GB3G2BL3E1174467      **License Number:** 26781      **Bus Number:** 5sb  
**Make of Body:** Starcraft      **Year:** 2014      **Make of Chassis:** Starcraft      **Year:** 2014  
**Bus Type:**      **Mileage:** 60672  
**Inspection Status:** R      **Inspected By:** Nate King      **PE:** 7421

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
2-1-4	LED type lights have 25% or more of the pixels inoperable in any one light

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description