## REPORT OF SCHOOL BUS INSPECTION

Type of Annual Date: 7/18/2019 Time: 11:30 AM

Name of School Corporation: AUXILIO SERVICES (MUNCIE) Corp ID: 251807

Address of School Corporation: 11260 Cornell Park Dr Suite 700

City:CincinnatiZip:45242County Number:18VIN:4DRBUC8P7JB524151License Number:Bus Number:M6Make of Body:IC Corporation Year:2016Make of Chassis:IC Corporation Year:2018

Bus Type: C Mileage: 24444

Inspection Status: R Inspected By: Jamie Hotchkiss PE: 6458

## Violations - Rejected

## <u>Inspection Code</u> <u>Description</u>

64-1-2 A lens is cracked, missing or wrong color

Any front turn signal does not function properly

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.