# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 7/19/2019 | **Time:** | 9:43 AM |
| **Name of School Corporation:** | JUST US KIDS INC (79) | | | **Corp ID:** | 79DC1 |
| **Address of School Corporation:** | 1494 Kalberer Rd | | | | |
| **City:** | West Laffayette | **Zip:** | 47906 | **County Number:** | 79 |
| **VIN:** | 1GB0G2BA0E1162049 | **License Number:** | B707J | **Bus Number:** | 3 |
| **Make of Body:** | Starcraft **Year:** 2014 | **Make of Chassis:** | Chevrolet | **Year:** | 2014 |
| **Bus Type:** | B | **Mileage:** | 14866 | | |
| **Inspection Status:** | R | **Inspected By:** | Nate King | **PE:** | 7421 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 16-1-1 | There are any leaks from the differential, pinion seal, hubs or wheel seals |
| 52-1-2 | Any shock absorber is leaking fluid |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**