REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Name of School Co Address of School	prporation: NO	ORTHERN WELLS	Date: COMM. SCHOOLS	7/25/2019 S	Time: Corp ID:	9:29 AM 908435
City: VIN:	4DRBUAAN45B9	Zip: 74486	License Number:	5764	County Number: Bus Number:	: 90 3
Make of Body: Bus Type:	IC Corporation Ye C	ear: 2004	Make of Chassis: Mileage:	IC Corporation 249232	Year:	2005
Inspection Status:	-	Inspected By:	Jamie Hotchkiss	LTULUL	PE:	6458

Violations - Rejected

Inspection <u>Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code	Description
59-2-1	Any stop arm light is inoperative

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.