

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	7/30/2019	<b>Time:</b>	10:38 AM		
<b>Name of School Corporation:</b>	NORTHEAST SCHOOL CORPORATION			<b>Corp ID:</b>	777645		
<b>Address of School Corporation:</b>	PO Box 493						
<b>City:</b>	Hymera	<b>Zip:</b>	47855	<b>County Number:</b>	77		
<b>VIN:</b>	4DRBUAAN7AB213011	<b>License Number:</b>	32097	<b>Bus Number:</b>	28		
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2009	<b>Make of Chassis:</b>	IC Corporation	<b>Year:</b>	2010
<b>Bus Type:</b>	C	<b>Mileage:</b>	175653				
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Byron Goodman	<b>PE:</b>	7008		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
95-1-10	Does not move smoothly or rest solidly on the ground

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**