REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Re-InspectionDate:8/2/2019Time:9:39 AMName of School Corporation:CARROLL CONS. SCHOOL CORP.Corp ID:80750

Address of School Corporation: 2 S 3rd St.

City: Flora Zip: 46929 County Number: 8
VIN: 4DRBUSKN8EB765918 License Number: 6222 Bus Number: 18
Make of Body: IC Corporation Year: 2014 Make of Chassis: IC Corporation Year: 2014

Bus Type: D Mileage: 75866

Inspection Status: A Inspected By: Nate King PE: 7421

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.