# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 8/6/2019 | **Time:** | 10:51 AM |
| **Name of School Corporation:** | NORTH GIBSON SCHOOL CORP. | | | **Corp ID:** | 262735 |
| **Address of School Corporation:** | 1108 N Embree St | | | | |
| **City:** | Princeton | **Zip:** | 47670 | **County Number:** | 26 |
| **VIN:** | 1GB6G5BG2E1199815 | **License Number:** | 8080 | **Bus Number:** | 234 |
| **Make of Body:** | Starcraft **Year:** 2014 | **Make of Chassis:** | Chevrolet | **Year:** | 2014 |
| **Bus Type:** | B | **Mileage:** | 10809 | | |
| **Inspection Status:** | A | **Inspected By:** | Bradley MIller | **PE:** | 7809 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**