REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 8/7/2019 Time: 9:24 AM

Name of School Corporation: SOUTH BEND COMM. SCHOOL CORP.

Corp ID: 717205

Address of School Corporation: 3003 N Bendix Dr

City:South BendZip:46601County Number:71VIN:4DRBUAAN0BB356433License Number:74968Bus Number:125Make of Body:IC Corporation Year:2011

Bus Type: C Mileage: 112010

Inspection Status: O Inspected By: Travis Harrold PE: 8022

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

The seat belt cutter is not located within the driver's view and reach
The seat belt cutter is not secured using a positive fastening method.

Violations - Out of Service

<u>Inspection Code</u> <u>Description</u>

59-2-1 Any stop arm light is inoperative

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.