REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	8/7/2019	**Time:**	9:24 AM
Name of School Corporation:	SOUTH BEND COMM. SCHOOL CORP.			**Corp ID:**	717205
Address of School Corporation:	3003 N Bendix Dr				
City:	South Bend	**Zip:**	46601	**County Number:**	71
VIN:	4DRBUAAN0BB356433	**License Number:**	74968	**Bus Number:**	125
Make of Body:	IC Corporation **Year:** 2010	**Make of Chassis:**	IC Corporation	**Year:**	2011
Bus Type:	C	**Mileage:**	112010		
Inspection Status:	O	**Inspected By:**	Travis Harrold	**PE:**	8022

Violations - Rejected

Inspection Code	Description
50-1-1	The seat belt cutter is not located within the driver's view and reach
50-1-2	The seat belt cutter is not secured using a positive fastening method.

Violations - Out of Service

Inspection Code	Description
59-2-1	Any stop arm light is inoperative

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.