REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Semi-AnnualDate:8/7/2019Time:9:45 AMName of School Corporation:HONEY GROVE EDUCATIONAL DAYCARECorp ID:41001Z

Address of School Corporation: 1709 S SR 135

City:GreenwoodZip:46143County Number:41VIN:1GBHG31RXX1146766License Number:B958ABBus Number:2Make of Body:Chevrolet Year:1999Make of Chassis:Chevrolet Year:1999

Bus Type: Mileage: 128074

Inspection Status: O Inspected By: Matt Lawrence PE: 6464

Violations - Rejected

Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the

bus body

Violations - Out of Service

Inspection Code Description

Audible warning device, when required, is not working properly. Buzzers are required

after 5-2-94

Bus Type Description