REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	8/7/2019	**Time:**	9:45 AM
Name of School Corporation:	HONEY GROVE EDUCATIONAL DAYCARE			**Corp ID:**	41001Z
Address of School Corporation:	1709 S SR 135				
City:	Greenwood	**Zip:**	46143	**County Number:**	41
VIN:	1GBHG31RXX1146766	**License Number:**	B958AB	**Bus Number:**	2
Make of Body:	Chevrolet **Year:** 1999	**Make of Chassis:**	Chevrolet	**Year:**	1999
Bus Type:		**Mileage:**	128074		
Inspection Status:	O	**Inspected By:**	Matt Lawrence	**PE:**	6464

Violations - Rejected

Inspection Code	Description
23-1-6	Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the bus body

Violations - Out of Service

Inspection Code	Description
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description