# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Semi-Annual | **Date:** | 8/7/2019 | **Time:** | 9:50 AM |
| **Name of School Corporation:** | CENTER GROVE COMM. SCHOOL CORP | | | **Corp ID:** | 414205 |
| **Address of School Corporation:** | 4900 W Stones Crossing Rd | | | | |
| **City:** | Greenwood | **Zip:** | 46143 | **County Number:** | 41 |
| **VIN:** | 1GBJG3125612385 | **License Number:** | 84490 | **Bus Number:** | 207 |
| **Make of Body:** | Mid Bus, Inc. **Year:** 2007 | **Make of Chassis:** | Chevrolet | **Year:** | 2007 |
| **Bus Type:** | | **Mileage:** | 52351 | | |
| **Inspection Status:** | A | **Inspected By:** | Matt Lawrence | **PE:** | 6464 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

| Bus Type Description |
|---|