## REPORT OF SCHOOL BUS INSPECTION

Type of Annual Time: 9:12 AM Date: 8/8/2019 Inspection:

Name of School 03003Z

HUMAN SERVICES INC. HEAD START Corp ID: Corporation:

**Address of School Corporation:** PO Box 119

County City: Clifford Zip: 47203 3 Number:

License VIN: 1GB3G3BG3D1149429 D463337 **Bus Number:** 1012 Number:

Make of Blue Bird Chevrolet Year: 2013 2013 Make of Body: Year: Chassis: Corporation

**Bus Type:** С Mileage: 57375

Inspected PE: Inspection Status: A Travis Coryea 5892 By:

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.