

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|------------------------|------------|-------------------------|-----------------------|
| Type of Inspection: | Re-Inspection | Date: | 8/20/2019 | Time: | 8:58 AM |
| Name of School Corporation: | NORTHEAST DUBOIS CO. SCH. CORP | | | Corp ID: | 192040 |
| Address of School Corporation: | 5379 E Main St | | | | |
| City: | Dubois | Zip: | 47527 | County Number: | 19 |
| VIN: | 1BAKFCKH95F227326 | License Number: | B512K | Bus Number: | 2 |
| Make of Body: | Blue Bird Corporation | Year: | 2004 | Make of Chassis: | Blue Bird Corporation |
| Bus Type: | D | Mileage: | 170791 | Year: | 2005 |
| Inspection Status: | R | Inspected By: | Mike Adams | PE: | 7407 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 23-1-3 | Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.