

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/22/2019	Time:	10:26 AM
Name of School Corporation:	NORTH CENTRAL PARKE COMM SCH CORP			Corp ID:	616375
Address of School Corporation:	1497 E STATE RD 47				
City:	MARSHALL	Zip:	47859	County Number:	61
VIN:	4DRBUAAN8AB247684			License Number:	6692
Make of Body:	IC Corporation	Year:	2009	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	54070	Year:	2010
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
7-2-8	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.