REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	8/22/2019	**Time:**	9:50 AM
Name of School Corporation:	EAST GIBSON SCHOOL CORPORATION				**Corp ID:**	262725
Address of School Corporation:	941 S Franklin St					
City:	Oakland City	**Zip:**	47660		**County Number:**	26
VIN:	1GB6G3AG8A1145550		**License Number:**	2370	**Bus Number:**	21
Make of Body:	Star Trans **Year:** 2010		**Make of Chassis:**	Chevrolet	**Year:**	2010
Bus Type:			**Mileage:**	76709		
Inspection Status:	O	**Inspected By:**	Bradley MIller		**PE:**	7809

Violations - Rejected

Inspection Code	Description
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly

Violations - Out of Service

Inspection Code	Description
34-2-2	Both lamps are inoperative on high beam

Bus Type Description