

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual		<b>Date:</b> 8/27/2019		<b>Time:</b> 9:46 AM	
<b>Name of School Corporation:</b> EAST GIBSON SCHOOL CORPORATION				<b>Corp ID:</b> 262725	
<b>Address of School Corporation:</b> 941 S Franklin St					
<b>City:</b> Oakland City		<b>Zip:</b> 47660		<b>County Number:</b> 26	
<b>VIN:</b> 1GB6G3AG8A1165037		<b>License Number:</b> 2369		<b>Bus Number:</b> 22	
<b>Make of Body:</b> Star Trans		<b>Year:</b> 2010		<b>Make of Chassis:</b> Chevrolet	
				<b>Year:</b> 2010	
<b>Bus Type:</b>		<b>Mileage:</b> 87787			
<b>Inspection Status:</b> A		<b>Inspected By:</b> Bradley Miller		<b>PE:</b> 7809	

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

Bus Type Description