REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	8/29/2019	**Time:**	9:13 AM
Name of School Corporation:		M.S.D. MOUNT VERNON				**Corp ID:**	656590
Address of School Corporation:		1000 W 4th St					
City:	Mt Vernon	**Zip:**	47620			**County Number:**	65
VIN:	1T7YU4E20F1283191			**License Number:**	7840	**Bus Number:**	35
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2014	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2015
Bus Type:	D			**Mileage:**	42238		
Inspection Status:	O	**Inspected By:**	Bradley MIller			**PE:**	7809

Violations - Rejected

Inspection Code	Description
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
50-1-2	The seat belt cutter is not secured using a positive fastening method.

Violations - Out of Service

Inspection Code	Description
59-2-6	LED type lights have 50% or more pixels inoperable in one light. (NOTE: one letter in the word “STOP” equals one light.)
59-2-3	Stop arm does not fully extend to a right angle to the bus

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.