

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/30/2019	Time:	10:01 AM
Name of School Corporation:	KNOX COMMUNITY SCHOOL CORP.	Corp ID:	757525		
Address of School Corporation:	2 Redskin Trail				
City:	Knox	Zip:	46534	County Number:	75
VIN:	1GB3GSBG3G1255796	License Number:	39394	Bus Number:	50
Make of Body:	Collins Bus Corporation	Year:	2016	Make of Chassis:	Chevrolet
Bus Type:	A2	Mileage:	37022	Year:	2016
Inspection Status:	O	Inspected By:	Nathan Sherer	PE:	7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
64-1-4	Any front turn signal does not function properly
55-1-6	See Notes: Any defect inspector deems a violation not listed
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.