## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	8/30/2019	Time:	8:50 AM
Name of School Address of Sch	I Corporation: M.S. ool Corporation:	D. MOUNT V 1000 W 4th			Corp ID:	656590
City:	Mt Vernon	Zip:	47620		County Number:	65
VIN:	1T7YU4E22F1283192		License Number:	7841	Bus Number:	19
Make of Body:	Thomas Built Buses, Year Inc.	: 2014	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2015
Bus Type:	D		Mileage:	84577		
Inspection Status:	0	Inspected By:	Bradley Miller		PE:	7809

## **Violations - Rejected**

Inspection Code	<u>Description</u>
59-1-4	LED type lights have 25% to 49% pixels inoperable in any one light. (NOTE: one letter in the word "STOP" equals one light

## **Violations - Out of Service**

<u>Inspection</u> <u>Code</u>	<u>Description</u>			
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).			
59-2-3	Stop arm does not fully extend to a right angle to the bus			

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.