

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	9/4/2019	Time:	9:15 AM
Name of School Corporation:	CAROUSEL PLAY & LEARN CENTER	Corp ID:	420002		
Address of School Corporation:	900 E. Montgomery Rd.				
City:	Greensburg	Zip:	47240	County Number:	16
VIN:	1GBHG31RX11215706	License Number:	B658BU	Bus Number:	1
Make of Body:	Collins Bus Corporation	Year:	2001	Make of Chassis:	Chevrolet
Bus Type:	A1	Mileage:	63463	Year:	2001
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
24-1-5	Any paint is badly faded or peeling

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.