

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 9/6/2019 **Time:** 8:58 AM
Name of School Corporation: DELAWARE COMM. SCHOOL CORP. **Corp ID:** 181875
Address of School Corporation: 7821 SR 3 N
City: Muncie **Zip:** 47303 **County Number:** 18
VIN: 4DRBUC8N8LB437392 **License Number:** 23136 **Bus Number:** 1950
Make of Body: IC Corporation **Year:** 2019 **Make of Chassis:** IC Corporation **Year:** 2020
Bus Type: C **Mileage:** 2644
Inspection Status: O **Inspected By:** Jamie Hotchkiss **PE:** 6458

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
67-1-2	Rims are bent or loose

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.